

ZA180A Zero air

Aire cero

Número de pieza: 30-1660 (230v) - UK |
30-1670 (230v) - EU | 30-1680 (110v) -
US




Descripción

Generando aire cero para gas del detector en aplicaciones de GC, el generador ZA180A elimina todos los hidrocarburos procedentes del aire comprimido antes de que entren en la instrumentación, con el fin de garantizar los mejores resultados en el detector.



Generator Details

- **Tipos de gas:** Aire
- **Compresor integrado:** Si



Características clave

- No produce aire para
- 0,1 ppm de contenido
- Funciona 24 horas al día, 7 días a la semana si es necesario
- Un generador puede suministrar varios instrumentos
- Pocas piezas móviles significan poco mantenimiento requerido y aseguran una larga vida del generador
- Se requiere una configuración mínima
- Garantía integral in situ de 12 meses

Especificaciones técnicas

	ZA180A
Tipo de gas	Aire
Flujo de gas máximo:	18L/min
Contenido de hidrocarburos:	0.1ppm
Pureza máxima:	0.1ppm THC
Tiempo de inicio:	40 Minutes
Consumo de energía:	770 Watts
Voltaje:	110 / 230 ± 10% VAC
Frecuencia:	60 Hz
Corriente:	2/4 Amps
Temperatura máxima de funcionamiento:	30°C / 86°F
Acreditaciones:	CE
Tamaño (HxAxD) en mm	880 x 430 x 410 mm
Tamaño (HxAxD) en pulgadas	34,6 x 16,9 x 16,1 inches
Peso del generador	64kg / 140,8lbs

[PEAK Protected]TM

Peak Scientific gas generators define the benchmark in reliability, convenience and performance in laboratories around the world, and come backed with a 12 month warranty. Beyond this period however you can ensure that your investment continues to be **[Protected]** by our comprehensive generator care cover.

Our world-class aftercare support packages deliver a program of scheduled preventative maintenance whilst giving you the reassurance of instant access to worldwide technical support and priority on-site response in the untimely event of a breakdown.

- For ordering parts visit: www.peakscientific.com/ordering/
- For service plans visit: www.peakscientific.com/service/service-plans/

Peak Scientific UK
Tel: +44 (0)141 812 8100
Fax: +44 (0)141 812 8200

Peak Scientific North America
Tel: +1-800-767-6532
Fax: +1-978-608-9503

Peak Scientific China
Tel: +86 21 5079 1190
Fax: +86 21 5079 1191
For a full list of our worldwide office locations, please visit:
Web: www.peakscientific.com
Email: discover@peakscientific.com

Peak Scientific's Quality Management System conforms to: ISO:9001

